

# Your site inspection

A look inside a real report

ANONYMISED REPORT EXCERPT

See how site photographs are marked up to communicate proposed equipment positions, dimensions and installation work.

---

## 01 Proposed equipment location

A marked-up site photograph shows the proposed battery, inverter and distribution-board positions.


---

## 02 Cable routes and site work

A second photograph records proposed board relocation and cable extensions.

Two annotated pages reproduced from an actual HELEVAC site inspection report. Customer details, original file labels and identifying references are omitted.

This is an excerpt, not a complete design, compliance approval or quotation. Findings and costs are specific to each home.

**Annotations:**

- 2.1m ht
- new db

**Annotations:**

- move switchboard to back of wall
- move energex cable to front
- extend PV cable till new inverter
- 4.2m
- new meter board